Circuit-breakers, disconnect switches

Rotary handles with door interlock for UL/CSA approved NA switches

Moeller SK1230-1157EN-NA					
For a max. shaft length o Part no. Article no. when ordered separately	f 60 mm Price see price list	Notes	Extremely narrow fittings Part no. Price Article no. see pr when ordered list separately		Notes
NZM1-XTVDV-60-NA 100667 NZM2-XTVDV-60-NA 100668 NZM3-XTVDV-60-NA 100669 NZM4-XTVDV-60-NA 100670		Door interlock Not defeated in the locked OFF position Door opening possible with active rotation beyond the 0 position. Cannot be combined with mechanical interlock External warning plate/ designation label can be clipped on NZMXTVDV-60-NA For a maximum shaft length of 60 mm Without shaft support Cannot be combined with NZMXDZ additional handle External warning plate/ designation label can be clipped on	NZM1-XTVDV-0-NA 100675 NZM2-XTVDV-0-NA 100676 NZM3-XTVDV-0-NA 100677 NZM4-XTVDV-0-NA 100678	1 off	Door interlock Not defeated in the locked OFF position Door opening possible with active rotation beyond the 0 position. Cannot be combined with mechanical interlock External warning plate/ designation label can be clipped on NZMXTVDV-0-NA For extremely narrow fittings With special short extension shaft Cannot be combined with NZMXDZ additional handle External warning plate/ designation label can be clipped on
NZM1-XTVDVR-60-NA 100671 NZM2-XTVDVR-60-NA 100672 NZM3-XTVDVR-60-NA 100673 NZM4-XTVDVR-60-NA 100674		Door interlock Not defeated in the locked OFF position Door opening possible with active rotation beyond the 0 position. Cannot be combined with mechanical interlock External warning plate/ designation label can be clipped on NZMXTVDVR-60-NA For a maximum shaft length of 60 mm Without shaft support Cannot be combined with NZMXDZ additional handle External warning plate/ designation label can be clipped on	NZM1-XTVDVR-0-NA 100679 NZM2-XTVDVR-0-NA 100680 NZM3-XTVDVR-0-NA 100681 NZM4-XTVDVR-0-NA 100682	1 off	Door interlock Not defeated in the locked OFF position Door opening possible with active rotation beyond the 0 position. Cannot be combined with mechanical interlock External warning plate/ designation label can be clipped on NZMXTVDVR-0-NA For extremely narrow fittings With special short extension shaft Cannot be combined with NZMXDZ additional handle External warning plate/ designation label can be clipped on