













ProLine


Subpanel

Panneau de montage

Panel adyacente



<p>1</p>  <p>(1x)</p>	<p>2</p>  <p>(1x) (2x)</p>	<p>3</p>  <p>(1x) (2x)</p>	<p>4</p>  <p>(2x) (3x)</p>	<p>5</p>  <p>(2x) (3x)</p>
<p>6</p> <p>M8</p>  <p>(2x) (3x)</p>	<p>7</p> <p>M8-1.25x16</p>  <p>(4x) (6x)</p>	<p>8</p> <p>M5x20</p>  <p>(4x) (6x)</p>	<p>9</p> <p>M8</p>  <p>(2x) (3x)</p>	
<p>10</p> <p>M6-1x16</p>  <p>(4x) (6x)</p>	<p>11</p> <p>M6</p>  <p>(2x) (3x)</p>			

<p>⚠ CAUTION ⚠ ATTENTION ⚠ PRECAUCIÓN</p>
<p>When shipping horizontally, an additional bracket (order separately) must be added, as shown, to prevent glide block damage.</p> <p>En embarquant horizontalement, un support additionnel (ordre séparément) doit être ajouté, comme montré, pour empêcher des dommages de bloc de glissement.</p> <p>Al enviar horizontalmente, una escuadra adicional (orden por separado) se debe agregar, según lo demostrado, para prevenir daño del bloque del deslizamiento.</p>


NOTE: Upper and lower brackets must mount over the same square hole.

NOTE: Les parenthèses supérieures et inférieures doivent monter l'excédent le même trou carré.

NOTE: Los soportes superiores y más bajos deben montar el excedente la misma perforación rectangular.

