

DMW BCD MOUNTING INSTALLATION

- 1) Drill through molded housing and steel channel at drill dimple in housing.
- 2) Install BCD parts as show below.

