





**NOTE:** The following instructions must be completed prior to hardwiring the box.  
**NOTE :** Les instructions suivantes doivent être accomplies avant de câbler la boîte.



**WIRING INSTRUCTIONS**  
**INSTRUCTIONS DE CÂBLAGE**

1. Make sure that the power from the main panel is switched off before starting installation or maintenance of electrical fixtures.
2. Remove the cover on the junction box.
3. Bring in a power supply line through the knockout.
4. Connect the green (or bare copper) wire.
5. Connect the white wire.
6. Connect the black wire.
7. Replace the junction box cover back in place.
8. Turn the power back on from the main panel.

1. Assurez-vous que l'alimentation du panneau principal est coupée avant de commencer toute installation ou maintenance d'appareils électriques.
2. Retirez le couvercle de la boîte de jonction.
3. Apportez une ligne d'alimentation par le biais de la débouchure.
4. Connectez le fil vert (ou cuivre nu).
5. Connectez le fil blanc.
6. Connectez le fil noir.
7. Remettez le couvercle de la boîte de jonction en place.
8. Rétablissez l'alimentation à partir du panneau principal.



**MOTION SENSOR SETTINGS**  
**PARAMÈTRES DU CAPTEUR DE MOUVEMENT**

**DETECTION AREA**  
**ZONE DE DÉTECTION**

	Dip switch Interrupteur DIP			
	1	2		
ON ↑	I	ON	ON	100%
	II	-	ON	75%
	III	ON	-	50%
	IV	-	-	10%

**HOLD TIME**  
**TEMPS DE MAINTIEN**

	DIP switch Interrupteur DIP			
	3	4	5	
ON ↑	I	ON	ON	5s
	II	-	ON	30s
	III	ON	-	90s
	IV	-	-	3min
	V	ON	ON	20min
	VI	-	-	30min

**MODE**  
**MODE**

	Dip switch Interrupteur DIP		
	9		
ON ↑	I	ON	Constant ON
	II	-	Sensor