## **Touchless AC Voltage Indicator**



- · Bright LED and audible alarm if voltage is present.
- Fast, easy, non-contact voltage detection.
- Adjustable sensitivity.
- Identifies hot and neutral conductors.
- Checks individual breakers for power.
- Accessories included: (1) 9V battery.
- Lifetime Limited Warranty.

34470

#### SPECIFICATIONS

Voltage Measurement		AC V 24-1000
Frequency		50-500Hz
Measurement Category		CAT III, 1000V
CAT. NO.	UPC NO.	DESCRIPTION

Touchless AC Voltage Indicator

## **Adjustable Non-Contact Voltage Detector**











- Adjustable to safely detect power and low voltage.
- Safely detects AC voltage without touching the bare conductor.
- · Adjustable for use on power wiring plus lighting, thermostats and other low voltage circuits.
- · Use to detect voltage in outlets, lighting fixtures, wires and cables.
- Finds breaks in wires.
- · Identifies hot and neutral conductors.
- · Low battery indication.
- · Accessories included: (1) 1.5V AAA battery.
- · Lifetime Limited Warranty.

### **SPECIFICATIONS**

Voltage De Frequency: Measurem		AC V 5-1000 50-500Hz CAT IV, 1000V	
CAT. NO.	UPC NO.	DESCRIPTION	
GT-16	12727	Adjustable Non-Contact Voltage Detector	

# **Non-Contact Self Testing Voltage Detector**











- · Design and assembled in USA.
- · Patented Automatic self-test verifies the integrity of the unit.
- Bright LEDs and audible alarm sound if voltage is present.
- Silent-mode feature for use in quiet settings.
- Safe, non-contact voltage detection.
- · Use to detect voltage in outlets, lighting fixtures, circuit breakers, wires, and cables or to find a break in a wire.
- Automatically turns off after five minutes of non-use to conserve battery life.
- · Low battery indicator.
- (2) 1.5V AAA batteries included.
- · Lifetime Limited Warranty.

### **SPECIFICATIONS**

AC V 50-1000 **Voltage Detection:** Frequency: 50-500Hz Measurement Category: **CAT IV, 1000V** 

CAT. NO.	UPC NO.	DESCRIPTION	
GT-12	20947	Non-Contact Self-Testing Voltage Detector	