CADDY ROD LOCK





CADDY ROD LOCK

CADDY ROD LOCK Beam Clamp

- Prefabricated assemblies easily lift and lock into place, helping to save time and money
- Easy "push-to-install" design allows installers to simply push the threaded rod through the mounting hole, instantly holding it in position
- Lock nut can be finger tightened, locking the rod in place
- Works with slightly damaged threads and minor burrs on the threaded rod
- Conforms with Federal Specification WW-H-171 (Type 23), Manufacturers Standardization Society ANSI*/MSS-SP-58 (Type 19 and 23)

Material: Cast Iron Finish: Electrogalvanized

	5	-	AFFROTED
Part Number	Description	F1*	F2*
CRLB37EG	3/8" Rod, 1/8"–3/8" Flange	250 lb	500 lb

*Static Load 1 represents 1/8" to 3/16" (3 mm to 5 mm) flange thickness. Static Load 2 represents 1/4" to 3/8" (6 mm to 10 mm) flange thickness.

For use on plain and electro zinc plated hardware only.

Recognizing that torque wrenches are generally not used or available on many job sites, the setscrew should be tightened so it contacts the I-beam and then an additional 1/2 turn added.

CADDY ROD LOCK Beam Clamp, Thick Flange

- Prefabricated assemblies easily lift and lock into place, helping to save time and money
- Easy "push-to-install" design allows installers to simply push the threaded rod through the mounting hole, instantly holding it in position
- Lock nut can be finger tightened, locking the rod in place
- Works with slightly damaged threads and minor burrs on the threaded rod
- Conforms with Federal Specification WW-H-171 (Type 23), Manufacturers Standardization Society ANSI*/MSS-SP-58 (Type 19 and 23)

Material: Cast Iron Finish: Electrogalvanized



Patent No.: 8,132,767 8,434,725



· · · · · · · · · · · · · · · · · · ·		AFFROTED		
Part Number	Description	F		
CRLB50EG	1/2" Rod, 3/8"–3/4" Flange	1,100 lb		
EN 40 American different and service the service service				

FM[®] Approved for top mount applications only.

For use on plain and electro zinc plated hardware only.

Recognizing that torque wrenches are generally not used or available on many job sites, the setscrew should be tightened so it contacts the I-beam and then an additional 1/2 turn added.



Patent No.: 8,132,767 8,434,725

(VL)_{US}