This circuit breaker is designed for use in bolt-on panelboard applications only.

This type of circuit breaker is available in one, two and three pole

A full complement of accessories is available. Some accessories require an additional pole space to the left side of the breaker. See Siemens Speedfax for information.

Note: Accessory installation must be completed before the breaker is mounted and connected (see instructions supplied with accessory before proceeding).

INSTALLATION

- A. Confirm that the device is suitable for the installation by comparing nameplate ratings with system requirements. Inspect the device for damage before mounting.
- B. Turn off and lock out all power supplying the panelboard before installing or servicing the circuit breaker.
 C. Device must be in "TRIPPED" or "OFF" position prior to mounting.
- D. To mount the device perform the following steps:
 - Position device on mounting rails. Rotate into position as shown in illustration Fig 1.
 - Install Line Terminal screw: recommended No. 10-32 washer head or equivalent screw with washer. Torque screw to 18-23 lbs-inch.
 - After mounting the device, load wiring and accessory terminals (if applicable) should be connected. Refer to breaker label for tightening torque requirements.
 - Recheck all line and load connector hardware for correct tgorque, and replace all covers, etc., in the panelboard before energizing the circuit.